

Appendix 2- Percentages for soil parameters for each sampling area

	Limaville	Lynnette	States	Nellabrook	Uniontown	East Tuscarawas	North Moreland	Lawrence	East Greenville	Justus	Harmon
Drainage Type											
Well drained	10.5	36.4	14.3	13.3	69.2	54.5	63.2	76	50	64	25
Moderately well drained	36.8	18.2	14.3	40	11.5	18.2	10.5	16	22.2	16	25
Somewhat poorly drained	36.8	27.3	42.9	26.7	3.8	18.2	15.8	8	16.7	12	37.5
Poorly drained	15.8	0	28.6	20	7.7	4.5	10.5	0	5.6	4	12.5
Very poorly drained	0	18.2	0	0	7.7	4.5	0	0	5.6	4	0
Depth to water table											
Above recommended range	10.5	36.4	14.3	13.3	69.2	54.5	63.2	76	50	64	25
In recommended range	21.1	0	14.3	26.7	0	9.1	5.3	12	5.6	12	0
Below recommended range	68.4	63.6	71.4	60	30.8	36.4	31.6	12	44.4	24	75
Capacity to transmit water											
Above recommended range	15.8	45.5	28.6	33.3	69.2	27.3	52.6	76	50	56	25
In recommended range	21.1	27.3	14.3	40	11.5	63.6	42.1	20	33.3	36	50
Below recommended range	63.2	27.3	57.1	26.7	19.2	9.1	5.3	4	16.7	8	25
Ratings for septic systems											
No to minor limitations	10	9.1	0	12.5	28.6	8.7	15	28	9.5	30.8	12.5
Minor to moderate	15	45.5	0	25	32.1	52.2	50	36	33.3	30.8	37.5
Moderate to severe	55	27.3	33.3	31.3	17.9	26.1	20	24	28.6	26.9	37.5
Severe to very severe	20	18.2	66.7	31.3	21.4	13	15	12	28.6	11.5	12.5