


Figure MS-2 Problem Areas - Main Stem Subwatershed

041100020305 Main Stem Subwatershed, Fish Creek
041100020305 Other Subwatershed, 12-Digit HUC
 Streams and Rivers
 Lakes
WWH Aquatic Life Use Designation

Land Use Related Concerns

- Altered Landscape/Hydrology
- Potential impacts due to proximity of land use (agriculture, golf courses, development)
- Altered Wetlands
- Neighborhood Flooding Reported
- ▲ Site on DERR (Division of Environmental Respos & Revitalization) database



Channel Conditions

Observations

Along Channel	At Sites	Condition
		Intact
		Recovering
		Eroding Channel
		Channelized
		Incised/alterned channel banks
		Impounded
		Dam

Dam removed/alterned between 2004 and 2010

